

Page 1 Of 3

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : \_\_\_\_\_ Signature : \_\_\_\_\_

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan  
 \*\* Record Time Daily \*\*                      Delays

[illegible]

**\*\*IMPORTANT NOTICE \*\***

**YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.**

Job Feedback/Historical Notes:



**IP7\_037472**

## \*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
-----	-----	-----	-----	---	-----	-----	-----
1 07339	REDUCER, 00.50 BUSHING	S 279345	03/25/04	EA	14	0	14
2 08211	COUPLING, 00.50 THREADED	S 279345	03/25/04	EA	10	0	10
3 08234	COUPLING, 00.50 THREADED	S 279345	03/25/04	EA	6	0	6
4 12537	NIPPLE, 00.50 THREADED	S 279345	03/25/04	EA	4	0	4
5 13513	NIPPLE, 00.375 THREADED	S 279345	03/25/04	EA	4	0	4
6 13516	NIPPLE, 00.50 THREADED	S 279345	03/25/04	EA	8	0	8
7 15280	NIPPLE, 00.50 THREADED	S 279345	03/25/04	EA	4	0	4
8 51171	FITTING, BRASS REDUCER	S 278975	03/23/04	EA	13	0	13
9 51285	FITTING, SS CONNECTOR	S 279340	03/25/04	EA	25	0	25
10 52262	CORD, LINE	S 277625	03/16/04	EA	4	0	4
11 53177	WIRE (MECH), TIE	S 279474	03/25/04	RL	2	0	2
12 74616	LIGHT, HARD HAT	S 279877	03/29/04	EA	2	0	2

IP7\_037473

CREW: 192

WORK ORDER TYPE: MODIFICATIONS

02-60456-66

ISSUE DATE 01/06/11

Page 3 Of 3

** Work Order Tools List **						
Ln	Tool No	Noun Qualifier	Measure 1	Measure 2	Measure 3	Rqd
1	2284	TAP, STARTER-PIPE	1/4"-18NPT			1
2	2202	TAP, STARTER-FRACTN	1/4"	20-NC	HIGH SPEED	1
3	2205	TAP, STARTER-FRACTN	1/4"	28-NF	HIGH SPEED	1

IP7\_037474